

Fig. 1A




Fig. 1B




Fig. 2




Fig. 3




Fig. 4

FIG. 5 is a schematic diagram of a control panel 12, showing a display 50 and a set of buttons 52a, 52b, 52c, and 52d. The display 50 shows a cursor 56 pointing to a button 60. A small square icon 54 is also visible on the display. A dashed box 58 is shown around the button 60. The panel is labeled 12, and the display area is labeled 50. The buttons are labeled 52a, 52b, 52c, and 52d. The cursor is labeled 56, and the button being pointed to is labeled 60. A small square icon is labeled 54, and a dashed box is labeled 58. The panel is also labeled 48.




Fig. 5




Fig. 6




Fig. 7






Fig. 8